

STATE OF HAWAII

DEPARTMENT OF HEALTH P.O. BOX 3378 HONOLULU, HAWAII 96801

June 9, 1999

In reply, please refer to: File:

To All Interested Parties:

SUBJECT: 1998 GROUNDWATER CONTAMINATION MAPS FOR THE

STATE OF HAWAII

Since August 1989, the Department of Health has been issuing the Groundwater Contamination Maps for the State of Hawaii. These maps identify locations where groundwater contaminants have been detected and confirmed.

We are enclosing information pertaining to the major health effects related to these contaminants. We emphasize that the detected levels reported in the maps are below existing Federal and State drinking water standards established for the protection of public health. Before contaminant levels reach these standards, we take appropriate public health protection measures.

The data presented in the maps and tables were collected between October 1996 through December 1998. Positive results are considered confirmed when verified by a different test or by the validation of historical data.

If you have any questions or would like to obtain additional information related to groundwater contamination, please contact the Groundwater Protection Program, Safe Drinking Water Branch, at (808) 586-4258.

Sincerely,

BRUCE S. ANDERSON, Ph.D., M.P.H.

Tune & Endurar

Director of Health

Enclosures

The Groundwater Contamination Maps for the State of Hawaii, 1998

Purpose

The Groundwater Contamination Maps identify organic chemical contaminants that have been detected and confirmed in wells used for drinking water, irrigation, and industrial purposes throughout the State. Groundwater can become contaminated through natural processes, but anthropogenic or human-induced contamination poses more serious problems. Contaminants may come from herbicides, pesticides, industrial solvents, and other sources applied, spilled, or leaked into the ground. Groundwater contamination is a significant concern because nearly all of Hawaii's drinking water comes from groundwater sources.

The intent of the maps is to identify only those wells with detectable levels of groundwater contamination. Some contaminated wells may not be reported because of the lack of confirmed data or wells have not been tested. The contamination levels in this document refer to reported levels of contamination on a specific sampling date. Levels of groundwater contamination may fluctuate for a number of reasons, including actual diminishing or increasing levels of contamination, chemical breakdown of contaminants, variability in sampling and analytical methods, the effects of pumping rates, and other factors.

Contents

This report consists of maps and tables for the islands of Kauai, Oahu, Maui, Molokai, Lanai, and Hawaii. The maps identify the locations of current and historic contaminated wells and wellfields (an area where many wells in proximity share the same groundwater source). The tables relate information about the contaminated well, such as the use of the well (e.g., drinking water, irrigation, industrial or unused), the contaminant detected, the concentration of the contaminant (e.g., detected level), the sampling date when contamination was detected, and drinking water standards and health risks associated with each contaminant. In cases where wellfields are identified, the well or pump in that wellfield with the highest concentration of a contaminant is reported.

Separate tables were prepared for wells that have updated monitoring information and for those that do not have current available information. This provides a better understanding of the contaminants presently being detected and their location. Historic information provides insight about contaminants detected and differences in past analytical methodologies, especially prior to established state and federal standards.

A contaminant which has been identified in prior editions will be removed from the report if subsequent monitoring no longer shows detection. A well will be removed from the map if it does not show any detectable concentrations of contamination. But a well and associated contaminant(s) will remain on the map until new information confirms that concentrations have decreased to non-detectable levels. This is the case with several non-drinking water wells in this report that are not monitored regularly.

The Groundwater Contamination Maps for the State of Hawaii, 1998

Reports of drinking water contamination are based on current State Department of Health (DOH) monitoring data for public drinking water wells. Other reports of contamination used in this document are from the State Department of Agriculture, the Hawaii Agricultural Research Center, and historic DOH data which may not be consistent with current monitoring and analytical standards.

Summary

In general, the concentration of chemical contaminants found in our wells have been detected at levels below State and Federal drinking water standards. These levels do not pose a serious health risk. The water from drinking water wells with detected contaminant concentrations that are increasing are closely monitored. If contamination levels approach State and Federal drinking water regulatory limits, steps are taken to assure public health and safety such as treatment methods to reduce concentrations to acceptable levels, or removing the well from service.

The following is a listing by island of the contaminants that have been detected in groundwater: (Refer to the pages on Applicable Drinking Water Standards for definitions of the acronyms.)

Oahu: Alachlor, Ametryn, Atrazine, Desethyl Atrazine, Despropyl Atrazine, Diamino

Atrazine, Chlordane, Dieldrin, DBCP, DCP, EDB, PCE, TCE, and TCP.

Maui: Ametryn, Atrazine, Desethyl Atrazine, Despropyl Atrazine, Diamino Atrazine,

Diuron, DBCP, EDB, Simazine, and TCP.

Hawaii: Atrazine, Desethyl Atrazine, Despropyl Atrazine, Diamino Atrazine, Hexazinone,

and Simazine.

Kauai: Ametryn, Atrazine, Desethyl Atrazine, and Simazine.

Molokai: None

Lanai: None.

Since the 1997 edition, no wells were taken off the maps because of the distinction between current and historic reporting. An addition for the 1998 edition is the Waipio Heights Wells on Oahu with detections of EDB and TCP. It should be noted that Carbon Tetrachloride was detected at the Kaluakoi Resort on Molokai in 1998, but a subsequent investigation found that detection of this contaminant did not occur at the groundwater source but occurred at locations on resort premises. Thus, the detection was not considered groundwater contamination.

The Groundwater Contamination Maps for the State of Hawaii, 1998

Definitions

The following are general definitions of the terms and abbreviations that are used in this report:

Concentration Level:

Refers to the amount of a contaminant found in a sample, the numerical values are presented in units of ppb (parts per billion).

ppb: This unit is commonly used as an equivalent to microgram per liter (ug/L). One ug/L is approximately a drop of contaminant in the volume of liquid contained in three Olympic size swimming pools.

Contaminant:

The contaminants identified in the report refer to chemical contaminants. DOH has defined contaminants as, "...any physical, chemical, biological, or radiological substance or matter in water. An additive contaminant under this definition may have a beneficial or detrimental effect on the potability of the water." (Hawaii Administrative Rules, Title 11, Department of Health, Chapter 20 Rules Relating to Potable Water Systems)

Detection Limit:

Refers to the lowest presence of a contaminant that can be detected by a laboratory through its testing equipment, analytical methods, and personnel.

ND:


Refers to non-detectable, or no presence of a contaminant at or below the detection limit used by a laboratory.

NO:

Refers to non-quantifiable, where a trace concentration of a contaminant was at a level greater than the detection limit but lower than the quantification limit used by a laboratory.

Quantification limit: refers to the level of contaminant concentration that can be confidently quantified by a laboratory's testing equipment, analytical methods, and personnel.

Groundwater Contamination on the Island of Oahu, 1998



This Map Contains the Latest Confirmed Results From Contaminated Groundwater Wells

See Table for Contaminant Information

GROUNDWATER CONTAMINATION ON THE ISLAND OF OAHU

| NO. WELL NAME USE CONTAMINANT LEVEL (in ppb) SAM | ATE PLED /27/98 /12/98 2/1/98 2/1/98 2/1/98 2/1/98 |
|--|--|
| 1 Dairy Co. (2600-02) DW TCE TCP | /27/98 /12/98 2/1/98 2/1/98 2/1/98 |
| TCP | /12/98 2/1/98 2/1/98 2/1/98 |
| 2 Hawaii Country Club (2603-01) DW DBCP before treatment after treatment A-0.02 ND 1. TCP before treatment after treatment after treatment after treatment A-0.2 ND 1. EDB before treatment A-0.2 ND 1. EDB before treatment A-0.2 ND 1. A-0.2 ND 1. A-0.4 NQ 8. A-0.5 NQ 1. A-0.6 NQ 1. A-0.5 NQ 1. A-0.5 NQ 1. A-0.6 NQ 1. A-0.5 NQ 1. A-0.6 NQ 1. A-0.5 NQ 1. A-0.6 NQ 1. A-0.5 NQ 1. A-0.5 NQ 1. A-0.6 NQ 1. A-0.5 NQ 1. A-0.6 NQ 1. A-0.7 NQ 1. A-0.7 NQ 1. A-0.8 NQ 1. A | 2/1/98 2/1/98 2/1/98 |
| A | 2/1/98 2/1/98 |
| A | 2/1/98 2/1/98 |
| TCP | 2/1/98 |
| ## A constraint after treatment before treatment after treatme | |
| EDB before treatment | 2/1/90 |
| A Hoaeae (2301-34 to 39) DW TCP C C C C C TCP | 25/98 |
| 3 Hoaeae (2301-34 to 39) DW TCP <0.5 NQ 1 4 Kaamilo St., Wells (2356-58 and 59) DW Dieldrin 0.014 5 Kaimuki (1748-03 to 10) DW Dieldrin 0.015 1 6 Kunia Wells I (2302-01 to 04) DW Atrazine 0.8 1 7 Kunia Wells II (2402-01,02,03) DW DBCP Defore treatment 40.02 ND 1 TCP Defore treatment 40.02 ND 1 TCP Defore treatment 40.02 ND 1 TCE Defore treatment 40.5 NQ 1 after treatment 40.5 NQ 1 TCE Defore treatment 40.5 ND 1 DW Drinking Water Well(s) IRR Trigation Well IND Industrial Well UNU Unused NQ Non-quantifiable ND Non-detected DCP Defore treatment 41.0 NQ 1 9 Mililani I (2800-01 to 04) DW DBCP Defore treatment 0.22 1 | /25/98 |
| 4 Kaamilo St., Wells (2356-58 and 59) DW Dieldrin 0.014 5 Kaimuki (1748-03 to 10) DW Dieldrin 0.015 1 6 Kunia Wells I (2302-01 to 04) DW Atrazine TCP 0.8 1 7 Kunia Wells II (2402-01,02,03) DW DBCP Defore treatment after treatment after treatment after treatment 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1. | 23/30 |
| 4 Kaamilo St., Wells (2356-58 and 59) DW Dieldrin 0.014 5 Kaimuki (1748-03 to 10) DW Dieldrin 0.015 1 6 Kunia Wells I (2302-01 to 04) DW Atrazine TCP 0.8 1 7 Kunia Wells II (2402-01,02,03) DW DBCP Defore treatment after treatment after treatment after treatment 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1. | 2/7/98 |
| 5 Kaimuki (1748-03 to 10) DW Dieldrin 0.015 1 6 Kunia Wells I (2302-01 to 04) DW Atrazine TCP 0.068 1 7 Kunia Wells II (2402-01,02,03) DW DBCP before treatment after treatment after treatment <0.04 NQ 1 | _, . , o o |
| 6 Kunia Wells I (2302-01 to 04) DW Atrazine TCP 0.068 1 7 Kunia Wells II (2402-01,02,03) DW DBCP before treatment after treatment CO.02 ND 1 TCP before treatment after treatment TCE before treatment Active treatment TCE before treatment Active treatment Not available for 12 8 Kunia Del Monte (2803-05 and 07) DW Carbon tetrachloride after treatment DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected 9 Mililani I (2800-01 to 04) DW DBCP before treatment CO.04 NQ 1 Active treatment Active treat | 4/1/98 |
| 6 Kunia Wells I (2302-01 to 04) DW Atrazine TCP 0.068 1 7 Kunia Wells II (2402-01,02,03) DW DBCP before treatment after treatment CO.02 ND 1 TCP before treatment after treatment CO.5 NQ 1 TCE before treatment after treatment CO.5 NQ 1 TCE before treatment After treatment Not available for 12 8 Kunia Del Monte (2803-05 and 07) DW Carbon tetrachloride after treatment CO.2 ND 1 TCE before treatment After treatment CO.2 ND 1 TCE before treatment CO.2 ND 1 TCE before treatment After treatment CO.2 ND 1 TCE before treatment After treatment CO.2 ND 1 TCE before treatment After treatment After treatment After treatment After treatment AC.2 ND 1 TCE before treatment After treatment AC.3 ND 1 TCE Before treatment After treatment AC.3 ND 1 TCE After treatment After treatment AC.3 ND 1 DCP Before treatment After treatment AC.3 ND 1 DCP Before treatment AC.3 ND 1 | |
| TCP | 1/4/98 |
| TCP | |
| 7 Kunia Wells II (2402-01,02,03) DW DBCP before treatment after treatment Not available for 12. 0.04 NQ 1.00.00 NQ | 1/6/98 |
| After treatment CO.02 ND 1 | 2/1/98 |
| After treatment CO.02 ND 1 | 0/7/00 |
| TCP before treatment 1.1 | 2/7/98 |
| TCE | 2/7/98 |
| TCE before treatment | 2/7/98 |
| 8 Kunia Del Monte (2803-05 and 07) DW Carbon before treatment 0.5 1. DW - Drinking Water Well(s) TCE before treatment 3.5 1. IND - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected DCP before treatment 4.0.2 ND 1. DW - Drinking Water Well(s) TCE before treatment 4.0.2 ND 1. DCP before treatment 4.0.2 ND 1. DCP before treatment 4.0.3 ND 1. DCP before treatment 4.0.3 ND 1. DCP before treatment 4.0.3 ND 1. | 2/7/98 |
| 8 Kunia Del Monte (2803-05 and 07) DW Carbon before treatment 0.5 1. DW - Drinking Water Well(s) tetrachloride after treatment | /21/98 |
| tetrachloride after treatment <0.2 ND 1. DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected | 21/98 |
| tetrachloride after treatment <0.2 ND 1. DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected | 2/1/98 |
| DW - Drinking Water Well(s) IRR - Irrigation Well IRD - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected DCP Defore treatment <0.2 ND 1. | 2/1/98 |
| ND - Industrial Well | 2/1/98 |
| UNU - Unused NQ - Non-quantifiable ND - Non-detected 9 Mililani I (2800-01 to 04) DCP before treatment <1.0 NQ 1 after treatment <0.3 ND 1 | 2/1/98 |
| ND - Non-detected after treatment < 0.3 ND - 1 9 Mililani I (2800-01 to 04) DW DBCP before treatment 0.22 1. | 2/1/98 |
| 9 Mililani I (2800-01 to 04) DW DBCP before treatment 0.22 1. | 2/1/98 |
| ' ' | |
| -0.00 ND 4 | 2/8/98 |
| | 2/8/98 |
| DCP before treatment <1.0 NQ 1. | 2/8/98 |
| | 2/8/98 |
| | 2/8/98 |
| after treatment <0.2 ND 1. | 2/8/98 |
| 40 MIII : II (0050 04 | 010100 |
| , , | 2/8/98 |
| | 2/8/98 |
| | 2/8/98 |
| | 2/8/98 |
| | 2/8/98 |
| after treatment <0.2 ND 1. | 2/8/98 |
| 11 BWS Halawa Wells Pump 1 and 2 DW Chlordane <0.3 NQ 1 | |
| · · · · · · · · · · · · · · · · · · · | 0/8/98 |
| (| 0/8/98 |
| | 0/8/98 8/5/98 |
| 12 Aiea Wells (2355-06 and 07) DW Dieldrin 0.014 1 | |

GROUNDWATER CONTAMINATION ON THE ISLAND OF OAHU

| | | | | - | DETECTED | | DATE |
|------|---|-----|-----------------------|--|--------------------|--------------|----------------------|
| NO. | WELL NAME | USE | CONTAMINAN | | LEVEL (in ppb) | | SAMPLED |
| (| Kamehameha Schools Wells 1 & 2 (2052-07 and 11) (only 2052-11 caken out of service) | DW | Chlordane Dieldrin | | <0.3 0.046 | NQ | 4/1/98 11/16/98 |
| | Kalihi Pumping Station (1952-06 to 08, 16-19, 22) | DW | Dieldrin | | 0.012 | | 10/13/98 |
| 15 E | Barbers Pt. Shaft (2103-03) | DW | Atrazine | | 0.088 | | 10/14/98 |
| 16 8 | Schofield Battery (2901-03, 04) | DW | TCE | before treatment | 18.5 <0.5 | NQ | 12/8/98 12/8/98 |
| | | | PCE | after treatment before treatment | <0.5 <0.5 | NQ | 12/8/98 |
| | | | FCE | | <0.2 | ND | 12/8/98 |
| | | | | after treatment | <0.2 | עוו | 12/0/90 |
| 17 V | Wahiawa Wells (2901-08, 11, 12) | DW | Carbon Tetrachlo | oride | <0.5 | NQ | 12/7/98 |
| ', ' | 77 41 11 47 6110 (2001 00, 11, 12) | ۷۷ | PCE | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | <0.5 <0.5 | NQ | 12/7/98 |
| | | | DBCP | | <0.04 | NQ | 8/25/98 |
| | | | DDOI | | ₹0.04 | 110 | 0/20/00 |
| 18 V | Waialua Wells (3405-01, 02) | DW | TCE | | <0.5 | NQ | 12/22/98 |
| | (| | TCP | | <0.5 | NQ | 12/22/98 |
| | | | DBCP | | <0.04 | NQ | 8/27/98 |
| | | | | | | | |
| 19 V | Waipahu I (2400-01, 02, 03, 04) | DW | EDB | before treatment | <0.04 | NQ | 12/2/98 |
| | | | | after treatment | <0.01 | ND | 12/2/98 |
| | | | TCP | before treatment | <0.5 | NQ | 12/2/98 |
| | | | TOF | after treatment | <0.2 | ND | 12/2/98 |
| | | | TCE | before treatment | <0.5 | NQ | 8/19/98 |
| | | | | after treatment | <0.2 | ND | 8/19/98 |
| 20 V | Waipahu II (2400-05, 06) | DW | EDB | before treatment | 0.04 | NQ | 12/2/98 |
| | | | | after treatment | Not availa | | |
| | DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused | | TCP | before treatment after treatment | <0.5 Not availa | NQ ble fo | 12/2/98 r 12/2/98 |
| | NQ - Non-quantifiable ND - Non-detected | | | | | | |
| 21 V | Waipio Hts. (2459-20) | DW | EDB | | <0.04 | NQ | 12/1/98 |
| | | | TCP | | <0.5 | NQ | 12/1/98 |
| | | | - - | | 10.0 | | , ., 00 |
| 22 V | Waipio Hts. II (2500-01, 02) | DW | TCE | | <0.5 | NQ | 11/13/98 |
| | Taken out of service) | • | TCP | | 0.8 | | 11/13/98 |
| • | , | | | | | | |
| 23 V | Naipio Hts. Wells III (2659-03) | DW | EDB | | < 0.04 | NQ | 1/22/98 |
| (| Taken out of service) | | TCP | | 0.6 | | 11/13/98 |
| _ | | | _ | | | | |
| 24 V | Wahiawa Wells II (2902-01) | DW | Carbon Tetrachlo | oride | <0.5 | NQ | 12/8/98 |
| | | | PCE | | 0.5 | NQ | 12/8/98 |
| | | | TCP | | <0.5 | NQ | 12/8/98 |
| 25 H | Jalaiwa Walla (2405 02, 04) | DW | DBCP | | 0.04 | | 12/15/98 |
| 20 1 | Haleiwa Wells (3405-03, 04) | שעע | TCP | | 0.04 <0.5 | NQ | 12/15/98 |
| | | | TCE | | <0.5 <0.5 | NQ | 9/9/98 |
| | | | | | νο.σ | . 13 | 3,3,30 |

GROUNDWATER CONTAMINATION ON THE ISLAND OF OAHU

| | I | I CO | NTAMINATION ON THE ISLAND (T | DETECTED | DATE |
|-------------------------|--|-----------------|--|-------------------------------------|--|
| NO. | WELL NAME | USE | CONTAMINANT | LEVEL (in ppb) | SAMPLED |
| 26 | Aina Koa Well (1746-01) | DW | Dieldrin | 0.013 | 11/4/98 |
| 27 | Waimanalo Well I (2043-02) (taken out of service) | UNU | Alachlor | 0.53 | 1/27/98 |
| 28 | Aiea Halawa Shaft (2255-32) (Navy Halawa Shaft) | DW | Chlordane Dieldrin | <0.30 NQ 0.011 | 1/9/98 4/7/98 |
| identi (No.) | ollowing are wells that have historic rified as (No.)H and H #. H refers to wells currently in use listed efers to wells that may or may not be | d by N e | o. on the preceding list. | | |
| (3)H | Hoaeae (2301-34 to 39) | DW | Atrazine Desethyl Atrazine | 0.063 <0.10 | 8/28/96 9/28/93 |
| (4)H | Kaamilo St., Wells (2356-58 and 59) | DW | PCE | 0.03 | 4/20/85 |
| (5)H | Kaimuki (1748-03 to 10) * Samples taken after this date do not show the from 0.01ppb to 0.2ppb. | DW presence | PCE e of this contaminant. Methodology changes | * 0.03 raised the detection for PCE | 4/23/85 |
| (6)H | Kunia Wells I (2302-01 to 04) | DW | Desethyl Atrazine TCP | <0.10 0.7 | 9/28/93 5/21/97 |
| (7)H | Kunia Wells II (2402-01,02,03) | DW | Atrazine Desethyl Atrazine | <0.10 <0.10 | 9/28/93 9/28/93 |
| (15)H | Barbers Pt. Shaft (2103-03) | DW | Desethyl Atrazine | 0.17 | 10/28/92 |
| (28)H | Aiea Halawa Shaft (2255-32) (Navy Halawa Shaft) | DW | Chlordane | <0.30 | 7/8/97 |
| H1 | Kunia Battery (2803-03 and 04) DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected | IND | Atrazine Desethyl Atrazine PCE TCE | 0.05 NQ 0.05 NQ 1.65 3.7 | 9/28/93 9/30/92 4/23/85 7/24/85 |
| H2 | Manana (2458-01) * Samples taken after this date do not show the from 0.01ppb to 0.2ppb. | DW presence | PCE e of this contaminant. Methodology changes | * 0.03 raised the detection for PCE | 4/18/85 |
| H3 | OSCO Ewa Pump 3 (2202-03) | UNU | Atrazine Desethyl Atrazine | <0.10 NQ 0.13 | 11/10/92 11/10/92 |
| H4 | OSCO Ewa Pump 5 (2202-05) | UNU | Atrazine Desethyl Atrazine | 0.15 0.14 | 11/10/92 11/10/92 |
| H5 | OSCO Ewa Pump 7A (2202-15) (also called Pump 8) | UNU | Atrazine Desethyl Atrazine | <0.10 NQ <0.10 NQ | 11/10/92 11/10/92 |


| | | 1 | ITAMINATION ON THE ISLAND (T | DETECTED | DATE |
|-------------|----------------------------------|-------|----------------------------------|-------------------|--------------|
| NO. | WELL NAME | USE | CONTAMINANT | LEVEL (in ppb) | SAMPLED |
| 110. | VVELETA VIVIE | OOL | | LL V LL (III ppo) | O/ (IVII EED |
| H6 | OSCO Ewa Pump 10 (2006-01 to 11) | UNU | Atrazine | <0.10 NQ | 11/17/92 |
| | , , | | Desethyl Atrazine | 0.15 | 11/17/92 |
| | | | | | |
| H7 | OSCO Ewa Pump 15 (2202-21) | UNU | Atrazine | 0.15 | 11/17/92 |
| | | | Desethyl Atrazine | 0.12 | 11/17/92 |
| | | | | | |
| H8 | OSCO Ewa Pump 20 (1900-01) | UNU | Atrazine | 0.71 | 11/16/93 |
| | | | Desethyl Atrazine | 1.2 | 11/16/93 |
| | | | Despropyl Atrazine | 0.13 | 11/16/93 |
| | | | Diamino Atrazine | 0.22 | 11/16/93 |
| | | | Ametryn | 0.05 NQ | 11/10/92 |
| H9 | OSCO Five Rump 24 (2000 04) | UNU | Atrazine | 0.77 | 11/16/93 |
| ПЭ | OSCO Ewa Pump 21 (2000-01) | UNU | Desethyl Atrazine | 0.77 | 11/16/93 |
| | | | Despropyl Atrazine | 0.13 | 11/16/93 |
| | | | Diamino Atrazine | 0.15 | 11/16/93 |
| | | | Diamino / Mazino | 0.20 | 11/10/00 |
| H10 | OSCO Ewa Pump 24 (1901-01) | UNU | Atrazine | 1.10 | 11/10/92 |
| | , , | | Desethyl Atrazine | 1.59 | 11/10/92 |
| | | | Despropyl Atrazine | 0.21 | 11/10/92 |
| | | | Diamino Atrazine | 0.50 | 11/10/92 |
| | | | Ametryn | 0.11 | 11/10/92 |
| | | | | | |
| H11 | Haleiwa Battery (3506-03) | IRR | Atrazine | 0.13 | 11/4/92 |
| | | | Lindane | 0.002 | 11/12/87 |
| L12 | Weiglin B2 Potton, (2207 01) | DW | Atrazine | 0.12 | 11/4/92 |
| ПІ | Waialua P2 Battery (3307-01) | טעט | | 0.12 | 11/4/92 |
| | | | Desethyl Atrazine | 0.15 | 11/4/92 |
| H13 | Waialua Sugar P3 (3505-01 to 20) | DW | DBCP | <0.04 NQ | 7/24/97 |
| | | | TCP | <0.5 NQ | |
| | | | | | .,, . |
| H14 | Waialua Sugar P17 (3404-02) | IRR | DBCP | 0.06 | 11/9/93 |
| | | | TCP | 1.1 | 11/9/93 |
| | | | | | |
| H15 | Waialua Sugar P24 (3102-02) | IRR | DBCP | 0.020 | 8/20/84 |
| | | | TCP | 0.500 | 6/3/85 |
| 1140 | W : 1 0 Doz (2000 04) | | | | 0/7/00 |
| H16 | Waialua Sugar P25 (3203-01) | IRR | DBCP | 0.115 | 6/7/83 |
| ⊔ 17 | Waialua Sugar P26 (3203-02) | IRR | DBCP | 0.012 | 6/3/85 |
| 1117 | Walalua Sugal F20 (3203-02) | IIXIX | TCP | 0.800 | 6/3/85 |
| | | | i Oi | 0.000 | 0/3/03 |
| H18 | Jonathan Springs Well (2025-12) | UNU | Chlordane | 0.3 | 11/8/95 |
| 5 | | | Dieldrin | 0.06 | 11/8/95 |
| | | | | 0.00 | , 3, 33 |
| H19 | Wilder Well 1 (1849-14) | DW | Dieldrin | 0.01☆ | 2/19/97 |
| | | | | | |

DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well

UNU - Unused

NQ - Non-quantifiable ND - Non-detected

⁻ latest monitoring results do not show the presence of this contaminant. This well will be removed from the list If the contaminant is not detected in subsequent monitoring (ideally through one annual weather cycle, including wet and dry seasons).




This map contains the latest confirmed results from contaminated groundwater wells

| | | | 1 | mom comamina | led groundwater went | |
|-----|---|-----|------------|------------------|------------------------|------------|
| | | | | | DETECTED | DATE |
| NO. | WELL NAME | USE | CONTAMINAN | NT | LEVEL (in ppb) | SAMPLED |
| | | | | | | |
| 1 | Kaanapali P4 (5739-01) | DW | TCP | before treatment | 0.5 | 12/10/98 |
| | | | | after treatment | <0.2 N | D 12/10/98 |
| | | | DBCP | before treatment | 0.04 | * 11/30/98 |
| | | | | after treatment | <0.02 N | D 11/10/98 |
| 2 | Kaanapali P5 (5738-01) | DW | TCP | before treatment | 1.4 | 12/10/98 |
| _ | Taariapan 1 0 (0700 01) | 2** | 101 | after treatment | | D 12/10/98 |
| | | | DBCP | before treatment | 0.18 | 11/10/98 |
| | | | 220. | after treatment | | D 11/10/98 |
| | | | | | | |
| 3 | Kaanapali P6 (5739-02) | DW | TCP | before treatment | 0.8 | 12/10/98 |
| | | | | after treatment | <0.2 N | D 12/10/98 |
| | | | DBCP | before treatment | 0.12 | 11/10/98 |
| | | | | after treatment | <0.02 N | D 11/10/98 |
| | DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused | | | | | |
| | NQ - Non-quantifiable ND - Non-detected | | | | * -resample of 11/10/9 | 8 |

GROUNDWATER CONTAMINATION ON THE ISLAND OF MAUI

| | | | TAWWATER ON THE IDEANS | DETECTED | DATE |
|-------------------------|--|----------------|---|--|---|
| NO. | WELL NAME | USE | CONTAMINANT | LEVEL (in ppb) | SAMPLED |
| ident (No.) | following are wells that have historic tified as (No.)H and H #.)H refers to wells currently in use liste refers to wells that may or may not be | ed by N | o. on the preceding list. | DW - Drinking Wate IRR - Irrigation Well IND - Industrial Well UNU - Unused NQ - Non-quantifiak ND - Non-detected | |
| H1 | Lahaina Pump A (5440-02) | IRR | Atrazine | 0.11 | 11/2/83 |
| H2 | Puunene Pump 7A (5227-04) | IND | Atrazine EDB | 1.0 0.040 | 7/29/85 3/12/85 |
| Н3 | Lower Paia #16 (5423-02) | IRR | Atrazine | 0.18 ♦ | 3/11/97 |
| H4 | Paia #7 (5422-02) | IRR | Atrazine EDB | 0.23 | 3/11/97 3/4/85 |
| H5 | Kuau Pump 12 (5522-01) | IRR | TCP | 0.430 | 3/4/85 |
| H6 | Maui High School (Old) (5420-01) | IRR | DBCP EDB TCP | 0.091 0.067 0.430 | 3/4/85 3/4/85 3/4/85 |
| H7 | Kaheka #18 (5321-01) | IRR | DBCP EDB TCP | 0.018 0.050 0.13 | 8/16/89 8/16/89 8/16/89 |
| Н8 | Napili A (Closed) (5838-01) | DW | DBCP | 0.360 | 6/4/93 |
| H9 | Maui Reynolds Well #1 (5228-06) (taken out of service) | DW | DBCP | <0.040 NC | |
| H10 | Kaanapali Pump D (5641-01) | IRR | Atrazine Ametryn Despropyl Atrazine Diamino Atrazine Simazine | 1.66 [♦] 1.4 0.12 0.15 0.82 | 3/11/97 6/1/93 6/1/93 6/1/93 6/1/93 |
| H11 | Puunene Pump 6 (5226-02) | IRR | Atrazine Desethyl Atrazine | 0.47 [♦] 0.23 | 3/11/97 3/15/94 |
| H12 | Puunene Pump 9 (5224-02) | IRR | Atrazine Desethyl Atrazine | 0.09 [♦] <0.10 NC | 3/11/97 6/15/93 |
| 13H | Kihei Well 1 (4727-01) | IRR | Atrazine Ametryn Desethyl Atrazine Diamino Atrazine | 0.54 ♦ <0.10 NC 0.32 <0.10 NC | 6/22/93 |
| 14H | Kihei Well 3 (4825-01) | IRR | Atrazine Desethyl Atrazine | 0.35 [♦] 0.19 ♦ | 3/11/97 3/15/94 |
| 15H | Puunene Mill Pump 19 (5227-05) | IRR | Atrazine Ametryn Desethyl Atrazine | 0.45 ♦ <0.10 ♦ NC 0.33 | 3/11/97 6/22/93 3/15/94 |
| | ♦ - DOA Immunoasay analysis | | Diamino Atrazine | <0.10 NC | |
| | | _ | | | |




| NO. | WELL NAME | USE | CONTAMINANT | DETECTED LEVEL (in ppb) | DATE SAMPLED |
|-----|---------------------------------|-----|----------------------|----------------------------|--------------------|
| 1 | Paauilo Well (6223-01) | DW | Atrazine | 0.62 | 10/8/98 |
| 2 | Laupahoehoe Wells (5814-01, 02) | DW | Atrazine | 0.20 | 10/8/98 |
| 3 | Kulaimano (5006-01) | DW | Atrazine | 0.37 | 10/8/98 |
| 4 | Keeau 1 (3802-01) | DW | Atrazine | 0.061 | 1/15/98 |
| 5 | Pahala (1229-01) | DW | Atrazine | 0.24 | 10/14/98 |
| 6 | Haina Well (6528-01) | DW | Atrazine | 0.1 | 10/8/98 |
| 7 | Olaa 3 (3603-01) | DW | Atrazine | 0.061 | 11/13/98 |
| 8 | Chaves Spring (5610-) | DW | Atrazine | 0.350 | 10/8/98 |
| 9 | Maukaloa Spring (5006-) | DW | Atrazine Simazine | 0.23 0.11 | 10/8/98 10/8/98 |

GROUNDWATER CONTAMINATION ON THE ISLAND OF HAWAII (continued)

| | GROUNDWATER CO | | INATION ON THE ISLAND OF HA | DETECTED | DATE |
|----------------|--|---|--|------------------------------|--|
| NO. | WELL NAME | USE | CONTAMINANT | LEVEL (in ppb) | SAMPLED |
| 10 | Kaiele Spring (4708-) | DW | Atrazine | 0.380 | 10/8/98 |
| 11 | Waiuliuli Spring (6734-01) | DW | Atrazine | 0.220 | 10/8/98 |
| 12 | Ninole A and B (0831-02, 03) | DW | Atrazine | 0.097 | 10/13/98 |
| 13 | Ookala Well (6017-05) | 0.590 | 10/8/98 | | |
| ident (No.) | following are wells that have historic ified as (No.)H and H #. IH refers to wells currently in use liste efers to wells that may or may not be | | | | |
| (2)H | Laupahoehoe Wells (5814-01, 02) | DW | Desethyl Atrazine Despropyl Atrazine Diamino Atrazine Hexazinone | 0.82 0.23 0.17 1.3 | 1/12/93 1/12/93 1/12/93 9/25/90 |
| (3)H | Kulaimano (5006-01) | DW | Hexazinone Diuron | 0.3 0.6 | 8/5/91 R 8/5/91 R |
| (4)H | Keeau 1 (3802-01) | DW | Desethyl Atrazine | 0.03 N | Q 12/15/92 |
| (5)H | Pahala (1229-01) | DW | Desethyl Atrazine | 0.19 | 12/18/92 |
| (6)H | Haina Well (6528-01) | DW | Desethyl Atrazine Diamino Atrazine | 0.38 0.11 | 1/12/93 1/12/93 |
| (7)H | Olaa 3 (3603-01) | DW | Desethyl Atrazine | 0.06 | 12/21/93 |
| (9)H | Maukaloa Spring (5006-) | DW | Hexazinone | 0.56 | 9/24/86 |
| (11)H | H Waiuliuli Spring (6734-01) | DW | Hexazinone | 0.72 | 9/9/85 |
| H1 | Paauilo Shaft (6321-02) | DW | Atrazine Hexazinone | 0.590 1.10 | 2/28/95 9/9/86 |
| H2 | Ookala Shaft (6117-07) (taken out of service) | DW | Atrazine Desethyl Atrazine Despropyl Atrazine Diamino Atrazine | 0.60 1.00 0.16 0.15 | 9/11/96 1/12/93 1/12/93 1/12/93 |
| НЗ | Hakalau School Well (5307-01) | DW | PCE | 0.130 [‡] | 5/6/85 |
| ર્ | - Samples taken since this date do contaminant. Methodology change PCE from 0.01 ppb to 0.2 | R - date receive DW - Drinkin IRR - Irrigatic IND - Industr UNU - Unused NQ - Non-qu ND - Non-de | g Water Well(s) on Well al Well antifiable | | |


| | | | | DETECTED | DATE |
|-----|--|-----|--|---|--|
| NO. | WELL NAME | USE | CONTAMINANT | LEVEL (in ppb) | SAMPLED |
| H4 | Pepeekeo Sugar Makai (5005-01) (HCPC Lower Well) | DW | Atrazine Desethyl Atrazine Hexazinone Diuron | <0.500 N 0.8 0.3 0.5 | NQ 1/22/96 12/14/93 8/5/91 R 8/5/91 R |
| H5 | Pepeekeo Sugar (5005-02) (HCPC Upper Well) | DW | Atrazine Desethyl Atrazine Despropyl Atrazine Diamino Atrazine Hexazinone Diuron | <0.500 N 1.2 0.15 0.14 0.9 0.8 | NQ 1/22/96 12/14/93 12/14/93 12/14/93 8/5/91 R 8/5/91 R |
| H6 | HCPC Makai Well 2 (5005-03) | DW | Atrazine Desethyl Atrazine | 0.27 0.22 | 12/1/92 12/1/92 |
| H7 | HPPC Makai Well (5005-04) | DW | Atrazine Desethyl Atrazine | 0.05 0.07 | 12/14/93 12/14/93 |
| H8 | Punaluu Th-2 (0830-02) | IRR | Atrazine Desethyl Atrazine | 0.12 0.16 | 12/21/93 12/21/93 |
| H9 | Keeau (1938-07) | IND | Atrazine Ametryn | 0.260 0.880 | 2/27/84 2/27/84 |
| H10 | Pahoa Battery (2986-01 and 02) (Pahoa Deep Well, Pump 1 and 2) | DW | Atrazine Desethyl Atrazine Diuron | 0.5 N 0.5 N 0.8 | · |
| H11 | Big Island Meat Co. (6323-01) | DW | Atrazine Desethyl Atrazine Despropyl Atrazine Diamino Atrazine | <0.500 N 0.55 0.15 0.12 | NQ 1/22/96 1/12/93 1/12/93 1/12/93 |
| H12 | Kaiaakea Spring (5611-) | DW | Hexazinone | 0.47 | 9/9/86 |
| H13 | Kihalani Spring (5613-) | DW | Hexazinone | 0.57 | 9/9/86 |
| H14 | Manowaiopae Spring (5814-) | DW | Atrazine | 0.14 | 10/23/96 |
| H15 | Papaaloa Spring (5713-) | DW | Atrazine | 0.560 | 2/28/95 |
| | DW - Drinking Water Well(s) IRR - Irrigation Well IND - Industrial Well UNU - Unused NQ - Non-quantifiable ND - Non-detected | | | R - date received by | / lab |

Groundwater Contamination on the Island of Kauai



| DATE SAMPLED | TECTED EL (in ppb) | | CONTAMINANT | USE | WELL NAME | NO. | | |
|-----------------|--|------------------------|---|-------------------|---|-----------------|--|--|
| 0/7/1998 | 53 1 | 0.053 | Atrazine | DW | Garlinghouse Tunnel (5823-01) | 1 | | |
| l I ble | DW - Drinking Wat IRR - Irrigation We IND - Industrial We NQ - Non-quantifia ND - Non-detected | IRR IND NQ | The following are wells that have historic monitoring information and are identified as (No.)H and H#. (No.)H refers to wells currently in use listed by No. on the preceding list. H# refers to wells that may or may not be currently used. | | | | | |
| 3/9/1993 | 0 NQ | <0.10 | Desethyl Atrazine | DW | Garlinghouse Tunnel (5823-01) | (1)H | | |
| l II ble | IRR - Irrigation We IND - Industrial We NQ - Non-quantifia ND - Non-detected | IRR IND NQ ND | No. on the preceding list. | ed by N curren | entified as (No.)H and H#. o.)H refers to wells currently in use liste f refers to wells that may or may not be | ide (N H# | | |

| NO | VA/ELL NIANAE | ПСЕ | CONTAMINANT | DETECTED | DATE |
|-----|-------------------------|-----|---------------------------------|--------------------------|-------------------------------|
| NO. | WELL NAME | USE | CONTAMINANT | LEVEL (in ppb) | SAMPLED |
| H1 | Barking Sands (0045-04) | IRR | Atrazine Ametryn Simazine | 3.5 0.80 0.20 | 7/12/88 7/12/88 7/12/88 |
| H2 | Paua Valley 2 (5942-01) | DW | Atrazine | 0.06 ♦ | 8/20/97 |
| НЗ | Kilohana C (5923-03) | DW | Atrazine | 0.15 ◊ | 8/20/97 |
| H4 | Kilohana G (5923-05) | DW | Atrazine | 0.22 ◊ | 8/20/97 |
| | | | | ♦ - DOA Immunoasay analy | rsis |
| | | | | | |



| NO. | WELL NAME | USE CONTAMINANT | DETECTED LEVEL (in ppb) | DATE SAMPLED |
|-----|--------------------|-----------------|----------------------------|-----------------|
| | | | | |
| NO | CONFIRMED CONTAMIN | NANTS DETECTED | | |
| | CONTINUED CONTAINI | | | |
| | | | | |
| | | | | |
| | | | | |

Applicable Drinking Water Standards, Possible Health Effects and Potential Sources of Groundwater Contamination

| Common Name | Applicable Drinking Water Standards (in ppb) (3) | | Possible Noncarcinogenic Effects. Based on Ingestion Effects on Animals (1) | EPA Carcinogen Rating (2) | Potential Contamination Sources |
|---|--|------------------|---|---------------------------------|--|
| Alachlor | 2 | MCL | Damaged red blood cells, causing kidney and speen damage | Probable | Herbicide |
| Ametryn | 60 | LHA | Liver Damage | Unclassified | Herbicide |
| Atrazine Desethyl Atrazine Despropyl Atrazi Diamino Atrazine | ne | MCL | Heart and liver damage;fetal/ child development retarded | Possible | Herbicide |
| Carbon Tetrachloride | 5 | MCL | Liver, kidney, and lung damage | Probable | Solvent,dry cleaning agent |
| Chlordane | 2 | MCL | Central nervous system, liver, kidney damage | Unclassified | Pesticide (termaticide) |
| 1,2 Dibromo- 3-chloropro- pane (DBCP) | 0.04 | SMCL | Male reproductive system, liver, and kidney damage | Probable | Pesticide (soil fumigant) |
| 1,1-Dichloro- ethylene (DCE) | 7 | MCL | Central nervous system depression; a heart effect; liver and kidney damage | Possible | Solvent |
| 1,2-Dichloro- propane (DCP) | 5 | MCL | Gastrointestinal irritation, liver and kidney damage | Probable | Pesticide, Solvent |
| Dieldrin | 0.002 | 10 ⁻⁶ | Central nervous system, liver, and kidney damage | Probable | Pesticide |
| Diuron | 10 | LHA | Central nervous system depression; damaged red blood cells, causing spleen damage; altered fetal development | Unclassified | Herbicide |
| Ethylene di- bromide (EDB) | 0.04 | SMCL | Male reproductive system, liver, gastrointestinal, and adrenal gland damage | Probable | Gas additive. soil fumigant, solvent |
| Hexazinone | 200 | LHA | Reduced body weight or possibly reduced growth | Unclassified | Herbicide |
| Lindane | 0.2 | MCL | Nerve damage and central nervous system seizures; liver and kidney damage; suppression of the immune system | Probable | Insecticide |

⁽¹⁾ Based on Health Advisories from the USEPA's Office of Drinking Water

⁽²⁾ Based on estimates from the USEPA's Health Hazard Assessment Group

⁽³⁾ See next page for definitions of Applicable Drinking Water Standards

Applicable Drinking Water Standards, Possible Health Effects and Potential Sources of Groundwater Contamination (continued)

| Common Name | Applicable Drinking Water Standards (in ppb) (3) | | Possible Noncarcinogenic Effects. Based on Ingestion Effects on Animals (1) | EPA Carcinogen Rating (2) | Potential Contamination Sources |
|-----------------------------------|--|------|---|---------------------------------|--|
| Simazine | 4 | MCL | Liver, kidney, and brain damage | Possible | Herbicide |
| Tetrachloro- ethylene (PCE) | 5 | MCL | Central nervous system depression; liver and kidney damage | Probable | Solvent, dry cleaning agent |
| Trichloro- ethylene (TCE) | 5 | MCL | Central nervous system depression; a heart effect; liver and kidney damage | Probable | Solvent |
| 1,2,3-Trichloro- propane (TCP) | 0.8 | SMCL | Decreased red blood cells; liver and kidney damage | Unclassified | Solvent, trace contaminant in certain pesticides |

⁽¹⁾ Based on Health Advisories from the USEPA's Office of Drinking Water

(3) Definition of Applicable Drinking Water Standards

"MCL"

means a maximum contaminant level or the maximum permissible level of a contaminant in water which is delivered to any user of a public water system. MCLs are the only federally enforceable drinking water standards.

"Lifetime Health Advisory" (LHA)

describes a non-regulatory concentration of a drinking water contaminant at which adverse health effects would not be anticipated to occur over a lifetime exposure of 70 years duration. The advisories are based on data describing non-carcinogenic risk from such exposure. This is a non-regulatory standard.

"SMCL"

describes the State's maximum contamination level (which may be more stringent than the MCL) of a contaminant in water and applies to community and non-transient non-community water systems, as defined in Hawaii Administrative Rules, Title 11, Department of Health, Chapter 20 - Rules Relating to Potable Water Systems.

"10-6"

indicates those chemicals which EPA considers to be potential human carcinogens. EPA estimates a "cancer risk level" as the level at which an individual who consumes water over his or her lifetime (70 years) would have no more than a one-in-a-million chance of developing cancer as a direct result of drinking water containing the contaminant. This is a non-regulatory standard.

⁽²⁾ Based on estimates from the USEPA's Health Hazard Assessment Group

⁽³⁾ See below for definitions of Applicable Drinking Water Standards